



Making Sense of Measurement



November 2024

Hello Reader,

CheckMate for SOLIDWORKS Version 1500 is Now Available

[\(Check out the Top 10 Videos\)](#)

and see v1500 IN ACTION

Take a look at our short what's new videos to see the new features/ enhancements

[Tech Tip 106](#)

Videos of GD&T Explained

Did you Know?

Be Up-to-date - Get Origin Blogs

Tech Tip 106

Setting Default Colour and Layer for New CheckMate Cad Geometry

Play (k)

Stay in the know by [subscribing to our blog](#).

You will be notified of upcoming update information.

TOP NOTCH



VIDEOS GD&T EXPLAINED

[Composite Tolerances Explained](#) -

*****MOST VIEWED*****

31,261 Views and Counting


4X \varnothing 6.0 \pm 0.025

\varnothing	\varnothing .020 (M)	C	E (M)	F (M)
	\varnothing .010 (M)	C		

[DRF Mobility Introduced](#)



Relationship Between Coords and True Position



* * * * *



Origin has removed the customer login from info.originintl.com.

The best ways to reach support are: email support@originintl.com

or call 1-800-420-7361

Note: our new phone number 416-945-2553



* * * * *

Be Up-to-Date

Get Origin Blogs



If you are using Origin software or are considering it, subscribe to our blogs.

Just click on one of the three blogs below and in the popup window that opens enter your email address...it's that easy

Origin International Inc. is focused on providing software solutions and consulting services to world class manufacturers, their suppliers and industry leading metrology solutions providers.

Manufacturers that choose Origin software solutions are industry leaders in innovation, quality and cost effectiveness within the Automotive, Aerospace, Transportation and Consumer Products industries.

If you would like more information, don't hesitate to contact us at 1-800-269-2509.

Sincerely,

The Origin Team

Origin International Inc.

sales@originintl.com support@originintl.com



Origin International, Incorporated, Richmond Hill, ON L4C 9B8, Canada

[Unsubscribe](#) [Manage preferences](#)